



## Legend

● Grab Sample Locations

### 50x50 Foot Soil Sample Grids

□ Below Action Levels

■ Exceeded Action Levels



## US EPA REGION 6

### FIGURE 4-1

SOIL SAMPLE EXCEEDANCE MAP  
LANE PLATING WORKS, INC.  
5322 BONNIE VIEW ROAD  
DALLAS, DALLAS COUNTY, TEXAS

TDD No: 5AWESTON-042-16-004  
CERCLIS ID: TXN000607031  
SOURCE: 2010 Microsoft Corporation and its data suppliers

Notes:  
Regional Screening Limits, May 2016 Industrial Soil (THQ=1.0)

DATE	PROJECT NO	SCALE
JULY 2016	20406.012.005.0992.01	AS SHOWN